

Figure 1





Figure 2



Prepare substrate layer - 210

200

Lay down metal trace - 220

Laminate on insulator layer - 230

Image insulator layer - 240

Etch insulator layer - 250

Fill compartment with resistor material - 260

Image insulator layer - 270

Etch insulator layer - 280

Fill compartment with capacitor material - 290

Add additional layer - 300




Figure 1.